

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR <small>Department of Transportation and Infrastructure</small>	<b>BRIDGE INSPECTION REPORT</b> <b>B07302024-10</b>
<b>Date:</b> 7/30/2024	<b>Inspected By:</b> Lars/Sarah	<b>Category:</b> Office - Bridge Office
<b>BRIDGE INFORMATION</b>		
<b>Site:</b>	3-056 - PETER'S ARM BROOK BRIDGE #2 - R350	
<b>SUBSTRUCTURE</b>		
<b>Condition:</b>	P3 - Poor	<b>Bearings:</b> U - Uninspectable
		<b>Bearing Seat:</b> F1 - Fair
<b>Comments:</b>	Undermining on North abutment (scour) Bearing seats covered in debris. Small amount of scour on south abutment showing an existing pile. Construction blocking left under diaphragms, making the bearing uninspectable.	
<b>SUPERSTRUCTURE</b>		
<b>Condition:</b>	F1 - Fair	<b>Expansion Joints:</b> P3 - Poor
<b>Comments:</b>	Joints filled with debris and leaking. All girders have low cover throughout. Leaking from expansion joints is making the outside reinforcement in the girders corrode and causing pop outs and scaling. Medium honeycombing on the bottom of a middle girder.	
<b>DECK</b>		
<b>Condition:</b>	F1 - Fair	<b>Curbs:</b> F1 - Fair
<b>Hand Rail:</b>	F1 - Fair	<b>Roadway Condition:</b> F1 - Fair
<b>Approach Rail:</b>	F1 - Fair	
<b>Comments:</b>	Minor cracks in curb. Minor cracks and efflorescence in soffit.	
<b>HYDROLOGY</b>		
<b>Water Velocity:</b>	0 m/s	<b>Ice Problem:</b> N - No Problem
<b>Water Depth:</b>	0 m	<b>Scour Problem:</b> K - Known Problem
<b>Waterway:</b>	01 - Adequate	<b>Debris Problem:</b> N - No Problem
<b>Comments:</b>	Slope erosion at all abutment corners. North abutment has medium scour 30-40% of the length, south abutment has a small amount of scour that is showing a pile (I beam).	
<b>REPLACEMENT/REHABILITATION</b>		
<b>Next Rehab. Date:</b>		<b>Replacement Year:</b>
<b>Antic. Rehab. Cost:</b>	\$0	<b>Replacement Cost:</b> \$0
<b>Recommendations:</b>		
<b>OBSERVATIONS</b>		
<b>Overall Condition:</b>	F1 - Fair	<b>Requires Further Inspection:</b> No
<b>Additional Observations:</b>	Overall F1 with slope erosion, abutment scour. Leaking joints causing girder deterioration, due to low cover throughout this will speed up in time.	