Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07152021-3				
Date: 7/6/2021			Category: Eng Eng				ngineering
BRIDGE INFORMATION	N						
Site:	3-093 - BOTTOM BRO	OK BRIDGE (PT LEAN	MINGTON)				
Route:	350		0	verall Leng	jth:	23.1 <b>m</b>	
Year Built:	1985	Est: No	0	verall Widt	h:	10.8 <b>m</b>	
Year Last Rehab.:		Est: No	R	loadway Wi	dth:	8.8 <b>m</b>	
Region:	CENTRAL WEST		S	idewalk Wi	dth:	0 <b>m</b>	
Jurisdiction:	Provincial		-	learance to	R.D. or	2 m	
Type of Structure:	04 - Rigid Frame		Μ	lax Depth o	f N.W.L.:	1 <b>m</b>	
Purpose of Structure:	04 - Over Non-Navigab	le Waters	S	pans:			
Type of Handrail:	01 - Aluminum Rail		<u>s</u>	Span No.:	Length	Span No.:	Length
Roadway Surface:	02 - Asphalt		1		12.5	4	0
Alignment Vertical:	01 - Good		2	2	0	5	0
Alignment vertical:						•	0
•	02 - Adequate		3	;	0	6	0
Alignment Horizontal:	02 - Adequate No		3		0	6	0
Alignment Horizontal: Restrictions: BRIDGE PHOTOS			3		0	6	0
Alignment Horizontal: Restrictions: BRIDGE PHOTOS			3		0 pplicable	6	0
Alignment Horizontal: Restrictions: BRIDGE PHOTOS	No			l - Ina		6	0
Alignment Horizontal: Restrictions: BRIDGE PHOTOS Internet Addition BRIDGE PHOTOS	No		earings:	l - Ina	pplicable	6	0
Alignment Horizontal: Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: Comments:	No		earings:	l - Ina	pplicable	6	
Alignment Horizontal: Restrictions:	No	B	earings:	I - Ina I - Ina	pplicable		
Alignment Horizontal: Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: SUPERSTRUCTURE Condition:	No	B	earings: earing Seat:	I - Ina I - Ina	pplicable		
Alignment Horizontal: Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: Comments: SUPERSTRUCTURE	No	B	earings: earing Seat:	I - Ina I - Ina	pplicable		
Alignment Horizontal: Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition: SUPERSTRUCTURE Condition: Comments: SUPERSTRUCTURE Condition: Comments:	No	Be cracks visible in aspha	earings: earing Seat:	I - Ina I - Ina	pplicable pplicable ninspectab		

Approach Rail:	F2 - Fair						
Comments:	One section of handrail needs to be repaired. Remainder of rail F2. One section of curb needs repair. Couple potholes on bridge. Approach rail not structural.						
HYDROLOGY							
Water Velocity:	0.5 <b>m/s</b>		Ice Problem:	N - No Prot	lem		
Water Depth:	0.6 <b>m</b>		Scour Problem:	N - No Prot	lem		
Waterway:	01 - Adequate		Debris Problem:	N - No Prot	lem		
Comments:							
REPLACEMENT/REHAB	ILITATION						
Next Rehab. Date:	2030		Replacement Yea	r: 2045			
Antic. Rehab. Cost:	\$100000		Replacement Cos	st: \$1500000			
Recommendations:	Handrail to be repaired by operations. Some asphalt patching needed and repair of deteriorated curb.						
OBSERVATIONS							
Overall Condition:	F2 - Fair		Requires Further Inspection:	No			
Additional Observations:	Watermain on structure.	No issues with pa	rking. hazards: traff	ic, water, slipping			
LEGEND: Condition Definitions: 1 - "Good - [discontinued code]. 2 - "Fair - [discontinued code]. 3 - "Poor - [discontinued code]. 4 - "Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelin Any nem which inspector, n Any emidence of known ice	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. P - Poor. seis spould ge documented by pno sing P3. P1, or C	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable.	Public).	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.		
INSPECTION PHOTOS							

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.