

GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B01132020-3

Date: 11/18/2019 Inspected By: Lynch R / Burge H Category: Eng. - Engineering

BRIDGE INFORMATION

Site: TCH-035 - SIR ROBERT BOND BRIDGE

Route:

 Year Built:
 1958
 Est: No

 Year Last Rehab.:
 2008
 Est: No

Region: CENTRAL WEST

Jurisdiction: Provincial

Type of Structure: 08 - Steel Bridge

Purpose of Structure: 03 - Over Navigable Waters

Type of Handrail: 01 - Aluminum Rail
Roadway Surface: 02 - Asphalt
Alignment Vertical: 02 - Adequate
Alignment Horizontal: 02 - Adequate

Restrictions: No

Overall Length: 191.8 m

Overall Width: 9 m
Roadway Width: 7.4 m

Sidewalk Width: 0 m

Clearance to R.D. or

N.W.L.:

Max Depth of N.W.L.: 3 m

Spans:

Span No.:	<u>Length</u>	Span No.:	Length
1	24.4	4	31.3
2	33.5	5	31.7
2	33.5	6	24 4

BRIDGE PHOTOS





SUBSTRUCTURE

Condition: F2 - Fair **Bearings:** U - Uninspectable

Bearing Seat: F2 - Fair

Comments: None or not enough rip rap upstream of pier #1.

SUPERSTRUCTURE

Condition: F2 - Fair **Expansion Joints:** F2 - Fair

Comments: Good

DECK

Condition: F2 - Fair Curbs: I - Inapplicable

Hand Rail: I - Inapplicable Roadway Condition: I - Inapplicable

F2 - Fair			
Hairline crack in underside of deck near abutment #2. Joint sealant cracked and/or missing in jersey barriers at expansion joints.			
0 m/s	Ice Problem:	N - No Problem	
0 m	Scour Problem:	N - No Problem	
01 - Adequate	Debris Problem:	N - No Problem	
ILITATION			
	Replacement Year:	:	
\$0	Replacement Cost	: \$0	
Add rip rap to pier #1 upstream (LHS)			
F2 - Fair	Requires Further Inspection:	No	
Could not get to piers or inside girders. Could not see bearings.			
F2 - Fair. C - Unsafe (Closed to F1 - Fair. U - Uninspectable. P3 - Poor. I - Inapplicable. P1 - Poor. P - Poor. bes below: ees should be documented by pnotograph ling P3, P1, P1, or C scour, debris, waterway problems	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable. Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.		
	Hairline crack in underside of deck near at expansion joints. 0 m/s 0 m 01 - Adequate **ILITATION** **Double The property of the property o	Hairline crack in underside of deck near abutment #2. Joint sea expansion joints. 0 m/s	

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.