



GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

**BRIDGE INSPECTION REPORT
B11062019-1**

Date: 11/6/2019

Inspected By: Alex Ford

Category: Eng. - Engineering

BRIDGE INFORMATION

Site:	2-026 - SALT POND BRIDGE #1				
Route:	220	Overall Length:	16.5 m		
Year Built:	1966	Est: No	Overall Width:	9.1 m	
Year Last Rehab.:	1987	Est: No	Roadway Width:	6.7 m	
Region:	CENTRAL EAST				
Jurisdiction:	Provincial				
Type of Structure:	02 - Double Tee	Clearance to R.D. or N.W.L.:	0.5 m		
Purpose of Structure:	04 - Over Non-Navigable Waters				
Type of Handrail:	01 - Aluminum Rail	Max Depth of N.W.L.:	1 m		
Roadway Surface:	02 - Asphalt	Spans:			
Alignment Vertical:	01 - Good	<u>Span No.:</u>	<u>Length</u>	<u>Span No.:</u>	<u>Length</u>
Alignment Horizontal:	01 - Good	1	10.4	4	0
Restrictions:	No	2	0	5	0
		3	0	6	0

BRIDGE PHOTOS





SUBSTRUCTURE

Condition:	P - Poor	Bearings:	P - Poor
		Bearing Seat:	P - Poor
Comments:	Significant deterioration of all components. Abutments have large cracking throughout and significant deterioration with concrete loss at all corners. The bearing seats are deteriorated to the point of bearing loss at some girder ends.		

SUPERSTRUCTURE

Condition:	P - Poor	Expansion Joints:	P - Poor
Comments:	Significant deterioration on most double tee girders, especially at the ends where some have concrete loss along the bottom edges near the bearing seats, compromising the bearing area. It appears some girders may be hanging from the deck slab with no contact with the bearing area. Both expansion joints are leaking badly and have been damaged by plow equipment.		

DECK

Condition:	P3 - Poor	Curbs:	P3 - Poor
Hand Rail:	F2 - Fair	Roadway Condition:	P3 - Poor
Approach Rail:	I - Inapplicable		
Comments:	Concrete deck with asphalt wearing surface. Some areas are leaking through deck, evidence of leakage on the underside. Aluminum hand rail and concrete end blocks in fair condition. Cracking and deterioration along sections of the curb. Roadway rough, especially at approaches.		

HYDROLOGY

Water Velocity:	0.5 m/s	Ice Problem:	N - No Problem
Water Depth:	Tidal m	Scour Problem:	N - No Problem
Waterway:	01 - Adequate	Debris Problem:	N - No Problem
Comments:	Tidal zone - water depths vary 0.3m to 1.5m		

REPLACEMENT/REHABILITATION

Next Rehab. Date:	2019	Replacement Year:	2019
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$500000
Recommendations:	This structure should be considered for immediate replacement. Propose using two aluminum pipe arch structures or an aluminum box culvert with full invert as replacement structure.		

OBSERVATIONS

Overall Condition:	P - Poor	Requires Further Inspection:	No
Additional Observations:			

LEGEND:

Condition Definitions:

1 - *Good - [discontinued code].
2 - *Fair - [discontinued code].

F2 - Fair.
F1 - Fair.

C - Unsafe (Closed to Public).
U - Uninspectable.

Problem Definitions:

N - No Problem.
P - Possible Problem.

Category Definitions:

Maint. - Maintenance.
Eng. - Engineering.

3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.	Office - Bridge Office.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.	
G - Good.	P - Poor.			

PHOTO GUIDELINES:
Inspection Photos:
 Please provide photos using guidelines below:

- Any item which inspector feels should be documented by photograph
- All items noted above as being P3, P1, P, or C
- Any evidence of known ice, scour, debris, waterway problems

INSPECTION PHOTOS

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.