Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure Inspected By: Kent Randell		BRIDGE INSPECTION REPORT B07062017-6				
Date: 6/22/2017				Category: Eng.			- Engineering
BRIDGE INFORMATION	l						
Site:	5-021 - WALSH RIVE	R BRIDGE					
Route:				Overall Leng	gth:	37.2 m	
Year Built:	1971	Est: No		Overall Widt	th:	11.1 m	
Year Last Rehab.:		Est: No		Roadway W	Roadway Width: 9.5 m		
Region:	LABRADOR			Sidewalk Wi	idth:	0 m	
Jurisdiction:	Provincial			Clearance to N.W.L.:	o R.D. or	3.1 m	
Type of Structure:	01 - AASH to Girder			Max Depth o	of N.W.L.:	0 m	
Purpose of Structure:	04 - Over Non-Naviga	ble Waters		Spans:			
Type of Handrail:	04 - Steel Rail			Span No.:	Length	Span No.:	Length
Roadway Surface:	02 - Asphalt			1	36	4	0
Alignment Vertical:	01 - Good			2	0	5	0
Alignment Horizontal:	01 - Good			3	0	6	0
U							
Restrictions: BRIDGE PHOTOS	No						
	No 2006/10/24		2006/10/24				
BRIDGE PHOTOS			2006/10/24				
Restrictions: BRIDGE PHOTOS SUBSTRUCTURE Condition:			2006/10/24 Bearings:	F2 - I	Fair		
BRIDGE PHOTOS	2005/10/24			F2 - F F2 - F			
BRIDGE PHOTOS	2005/10/24		Bearings: Bearing Seat:	F2 - I	Fair	nor deteriorat	ion on wes
BRIDGE PHOTOS	2005/10/24	I	Bearings: Bearing Seat:	F2 - I	Fair	nor deteriorat	on on wes
BRIDGE PHOTOS	2005/10/24	I ent in wing wall. 2" ren	Bearings: Bearing Seat:	F2 - I	Fair ing wall. Mi	nor deteriorat	on on wes
BRIDGE PHOTOS	F2 - Fair No additional movem end beam seat.	I ent in wing wall. 2" ren	Bearings: Bearing Seat: nains Some alligator o	F2 - F	Fair ing wall. Mi	nor deteriorat	on on wes
BRIDGE PHOTOS	F2 - Fair No additional movem end beam seat.	I ent in wing wall. 2" ren	Bearings: Bearing Seat: nains Some alligator o	F2 - F	Fair ing wall. Mi	nor deteriorat	ion on wes
BRIDGE PHOTOS	F2 - Fair No additional movem end beam seat.	I ent in wing wall. 2" rem	Bearings: Bearing Seat: nains Some alligator o	F2 - F	Fair ing wall. Mi Fair	nor deteriorat	ion on wes

Approach Rail:	F2 - Fair							
Comments:	Replace two lengths handrail 8m each. Concrete deterioration beneath 4 rail uprights. See photo Repair							
Comments.	approach posts.							
HYDROLOGY								
Water Velocity:	0 m/s	Ice Problem:	N - No Problem					
Water Depth:	0 m	Scour Problem:	N - No Problem					
Waterway:	01 - Adequate	Debris Problem:	N - No Problem					
Comments:								
REPLACEMENT/REHABILITATION								
Next Rehab. Date:	2017	Replacement Year:	2017					
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0					
Recommendations:	Bridge office to determine rehabilitation int	o.						
OBSERVATIONS								
Overall Condition:	F2 - Fair	Requires Further Inspection:	No					
Additional Observations:	Remove debris from bearing seat. Clean w	vinter sand from deck an	d curbs.					
LEGEND: Condition Definitions: 1 - "Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guidelin • Ally them which inspector for • Ally them which inspector for for your for • Ally them which inspector for for your for	F2 - Fair. C - Unsafe (Closed to F1 - Fair. U - Uninspectable. P3 - Poor. I - Inapplicable. P1 - Poor. P - Poor. es below: ests should be documented by pnotograph scour, debris, waterway problems	Public). N - No P - Po K - Kı	em Definitions: Category Definitions: o Problem. Maint Maintenance. ossible Problem. Eng Engineering. nown Problem. Office - Bridge Office. Not Applicable.					
Description:	Description:		Description:					
	Department of Transportation and Infrastructure,	Government of Newfoundland and	Labrador 2021					