
Appendix 25

Remediation Drawings



LEGEND BER

- BERRY SAMPLE LOCATION (STANTEC 2009)
- SURFACE SOIL SAMPLE (STANTEC 2009)
- O SURFACE DEBRIS LOCATION (STANTEC 2009)
- ♦ SMALL MAMMALS (STANTEC 2009)
- FISH LOCATION (STANTEC 2009)
- △ SURFACE WATER SAMPLE (STANTEC 2009)
- SEDIMENT SAMPLE (STANTEC 2009)
- ▲ VEGETATION SAMPLE LOCATION (STANTEC 2009)
- BENTHIC INVERTEBRATE SAMPLE (STANTEC 2009)
- TEST PIT (STANTEC 2009)
- TEST PIT (AGRA 1999)
- MONITOR WELL (STANTEC 2009)

ESTIMATED AREA OF METALS
IMPACTED SOIL, METALS AND OTHER
DEBRIS REQUIRING REMEDIATION



CAMP ROAD-FS


09-SWM2

SSM-2-CR

09-BENTHIC2

LAKE MELVILLE

CAMP ROAD DUMP SITE





ASSUMED DIRECTION OF GROUNDWATER FLOW



JULY 6, 2010

NOTE: THIS DRAWING ILLUSTRATES SUPPORTING INFORMATION SPECIFIC TO A STANTEC CONSULTING LTD. REPORT AND MUST NOT BE USED FOR OTHER PURPOSES.

NEWFOUNDLAND AND LABRADOR
DEPARTMENT OF ENVIRONMENT AND CONSERVATION

PROJECTITUS PHASE III ESA, HUMAN HEALTH AND ECOLOGICAL RISK ASSESSMENTS, REMEDIAL ACTION PLAN FOR THE FORMER U.S. MILITARY FACILITY OF NORTHWEST POINT, NL

ESTIMATED AREA OF METALS IMPACTED SOIL, METALS AND OTHER DEBRIS REQUIRING REMEDIATION - CAMP ROAD DUMP SITE

DRAWING No. 121410105-EE-25B

CAO FILE: 1044857-EE-21.DWG

1:1500

N.M



06JUL10 11:00AM

