



Location 15: Hydrocarbon stained fracture and bedding surfaces within parted to ribbon limestones of the Green Point Formation, Cow Head Group; at Broom Point. Larry Hicks (DNR) photo