



Location 16:- Hydrocarbon stained fracture and bedding surfaces within parted to ribbon limestones of the Green Point Formation, Cow Head Group; at Green Point. Larry Hicks (DNR) photo