

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B06082023-9	
Date: 5/28/2023		Inspected By: M Button/S Walsh		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		TCH-190 - BIFURCATION OVERPASS EAST - R1			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	F1 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	Light corrosion on all bearings, F1. - Remainder appears to be in good condition with very minor cracks, F2.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	F1 - Fair		
Comments:	Light corrosion on expansion joints, F1. - Remainder appears to be in good condition, F2.				
DECK					
Condition:	F2 - Fair	Curbs:	I - Inapplicable		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F1 - Fair				
Comments:	Damage on approach guiderail posts, F1.				
HYDROLOGY					
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:	2033	Replacement Year:	2068		
Antic. Rehab. Cost:	\$100000	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	F1 - Light corrosion on all bearings and expansion joints. - Remainder appears to be in good condition, F2.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.