

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B06082023-10
Date: 5/28/2023	Inspected By: M Button/S Walsh	Category: Office - Bridge Office
BRIDGE INFORMATION		
Site:	TCH-191 - BIFURCATION OVERPASS WEST - R1	
SUBSTRUCTURE		
Condition:	F2 - Fair	Bearings: F1 - Fair
		Bearing Seat: F2 - Fair
Comments:	Light corrosion on all bearings, F1. - Remainder appears to be in good condition with very minor cracks, F2.	
SUPERSTRUCTURE		
Condition:	F2 - Fair	Expansion Joints: F1 - Fair
Comments:	Light corrosion on expansion joints, F1. - Remainder appears to be in good condition, F2.	
DECK		
Condition:	F2 - Fair	Curbs: I - Inapplicable
Hand Rail:	F2 - Fair	Roadway Condition: F2 - Fair
Approach Rail:	F1 - Fair	
Comments:	Damage on approach guiderail posts, F1.	
HYDROLOGY		
Water Velocity:	n/a m/s	Ice Problem: NA - Not Applicable
Water Depth:	n/a m	Scour Problem: NA - Not Applicable
Waterway:	03 - Not Applicable	Debris Problem: NA - Not Applicable
Comments:		
REPLACEMENT/REHABILITATION		
Next Rehab. Date:	2033	Replacement Year: 2068
Antic. Rehab. Cost:	\$100000	Replacement Cost: \$0
Recommendations:		
OBSERVATIONS		
Overall Condition:	F2 - Fair	Requires Further Inspection: No
Additional Observations:	F1 - Light corrosion on all bearings and expansion joints. - Remainder appears to be in god condition, F2.	

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.