

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B12092025-1	
Date: 11/25/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-196 - BROWNSDALE RIVER BRIDGE #2 - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	Cribbing in fair condition with no significant defects observed. Bearings jammed at Abutment #1.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	F2 - Fair		
Comments:	Floor beams, stringers, and bracing in good overall condition. Main truss panels above deck level in fair condition. All pins have light corrosion, F2. Bridge has gaps for expansion.				
DECK					
Condition:	F2 - Fair	Curbs:	P3 - Poor		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F1 - Fair				
Comments:	One hazard marker missing. No end blocks. Approach rails in poor to fair condition with minor dents, scrapes, and rotten posts. Structure railing is 8x8 hardwood equipped with flexrail. No observed defects. Timber curb/wheel guard has local sections with the member missing, P3. Accumulation of sediment on deck restricted visual inspection.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	K - Known Problem		
Water Depth:	0 m	Scour Problem:	P - Possible Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Replace all hazard signs and deteriorated curb/wheel guard timbers.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.