

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11132024-13	
Date: 11/13/2024		Inspected By: Lars/Sarah		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-150 - CAPE BROYLE BRIDGE - R			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Narrow cracking through wing walls				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:					
DECK					
Condition:	F2 - Fair	Curbs:	I - Inapplicable		
Hand Rail:	F2 - Fair	Roadway Condition:	F1 - Fair		
Approach Rail:	P3 - Poor				
Comments:	Narrow cracking throughout barrier. Minor potholes on wearing surface. Approach rail posts have medium rot and minor dents in guide rail.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Missing 2 hazard signs. Major slope erosion under concrete gutter.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.