

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11132024-2	
Date: 11/13/2024		Inspected By: Lars/Sarah		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-178 - CROCKER'S BRIDGE - R11			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Assuming condition below water face of frame legs fair. Some efflorescence at joint between leg and wing wall at all 4 locations. Plywood also seems to be left in the joint in at least 1 location.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Some narrow cracks at haunch.				
DECK					
Condition:	F1 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F1 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F1 - Fair				
Comments:	Approach rails fair with minor damage to posts and minor corrosion. Minor dents in railing. Map cracking throughout end blocks and sidewalk. Minor cracks in fascia.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Bridge in fair condition with minor cracking observed.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.