

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		<b>BRIDGE INSPECTION REPORT</b> <b>B07122024-2</b>	
Date: 7/12/2024		Inspected By: L Christensen		Category: Office - Bridge Office	
<b>BRIDGE INFORMATION</b>					
Site:		1-267 - HARBOUR BRIDGE - R			
<b>SUBSTRUCTURE</b>					
Condition:	P3 - Poor	Bearings:	U - Uninspectable		
		Bearing Seat:	U - Uninspectable		
Comments:	Creosote timber abutment and wingwalls - mild face rot with hollow rotten centers where the ends exposed to water. Old timbers appear to have been repaired/replaced at south east retaining wall.				
<b>SUPERSTRUCTURE</b>					
Condition:	F1 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Medium corrosion to steel I beams.				
<b>DECK</b>					
Condition:	F2 - Fair	Curbs:	I - Inapplicable		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:	All new timber deck, curbs and guardrails installed. No hazard markers				
<b>HYDROLOGY</b>					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
<b>REPLACEMENT/REHABILITATION</b>					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
<b>OBSERVATIONS</b>					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Deck recently replaced. Substructure in weakest condition. Not department's responsibility				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.