

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B12182025-2	
Date: 12/18/2025		Inspected By: Megan/Heidi		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		1-170 - HODGE RIVER BRIDGE - R81			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Hairline pattern and horizontal cracking with light efflorescence in wingwalls. Wet pattern map cracking in abutment walls.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Hairline pattern cracking in soffit. Cracks with efflorescence in interior soffit and exterior fascia.				
DECK					
Condition:	F2 - Fair	Curbs:	F2 - Fair		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	G - Good				
Comments:					
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Refer to detailed OSIM inspection in BMS.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.