

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Works	<b>BRIDGE INSPECTION REPORT</b> <b>B07302018-4</b> Printed: Tuesday, October 2, 2018	
<b>Date:</b> 7/23/2018	<b>Inspected By:</b> Parsons R	<b>Category:</b> Maint. - Maintenance	
<b>BRIDGE INFORMATION</b>			
<b>Site:</b>	1-083 - WESTERN BAY BROOK BRIDGE NO.1		
<b>Route:</b>		<b>Overall Length:</b>	25.8 m
<b>Year Built:</b>	1970	<b>Est:</b> No	<b>Overall Width:</b> 10.8 m
<b>Year Last Rehab.:</b>		<b>Est:</b> No	<b>Roadway Width:</b> 6.3 m
<b>Region:</b>	AVALON PENINSULA	<b>Sidewalk Width:</b>	0 m
<b>Jurisdiction:</b>	Provincial	<b>Clearance to R.D. or N.W.L.:</b>	6 m
<b>Type of Structure:</b>	02 - Double Tee	<b>Max Depth of N.W.L.:</b>	1 m
<b>Purpose of Structure:</b>	04 - Over Non-Navigable Waters	<b>Spans:</b>	
<b>Type of Handrail:</b>	04 - Steel Rail	<u>Span No.:</u>	<u>Length</u>
<b>Roadway Surface:</b>	02 - Asphalt	<u>Span No.:</u>	<u>Length</u>
<b>Alignment Vertical:</b>	01 - Good	1	10.6
<b>Alignment Horizontal:</b>	02 - Adequate	2	0
<b>Restrictions:</b>	No	3	0
		4	0
		5	0
		6	0
<b>BRIDGE PHOTOS</b>			
			
<b>SUBSTRUCTURE</b>			
<b>Condition:</b>	F2 - Fair (Inspection within 2 Years)	<b>Bearings:</b>	G - Good (Inspection within 2 Years)
		<b>Bearing Seat:</b>	G - Good (Inspection within 2 Years)
<b>Comments:</b>	- Some scouring of footings and undermining.		
<b>SUPERSTRUCTURE</b>			
<b>Condition:</b>	F2 - Fair (Inspection within 2 Years)	<b>Expansion Joints:</b>	F2 - Fair (Inspection within 2 Years)
<b>Comments:</b>	- Expansion joints paved over. - Beams in good shape. - Cracks over expansion joints.		
<b>DECK</b>			
<b>Condition:</b>	F2 - Fair (Inspection within 2 Years)	<b>Curbs:</b>	F2 - Fair (Inspection within 2 Years)
<b>Hand Rail:</b>	F1 - Fair (Inspection within 1 Year)	<b>Roadway Condition:</b>	F2 - Fair (Inspection within 2 Years)

<b>Approach Rail:</b>	G - Good (Inspection within 2 Years)		
<b>Comments:</b>	- Deterioration of curbs and rail footings. - Rails rusted and in poor shape.		
<b>HYDROLOGY</b>			
<b>Water Velocity:</b>	0 m/s	<b>Ice Problem:</b>	P - Possible Problem
<b>Water Depth:</b>	1.0 m	<b>Scour Problem:</b>	K - Known Problem
<b>Waterway:</b>	01 - Adequate	<b>Debris Problem:</b>	P - Possible Problem
<b>Comments:</b>			
<b>REPLACEMENT/REHABILITATION</b>			
<b>Next Rehab. Date:</b>	2018	<b>Replacement Year:</b>	2018
<b>Antic. Rehab. Cost:</b>	\$0.00	<b>Replacement Cost:</b>	\$0.00
<b>Recommendations:</b>			
<b>OBSERVATIONS</b>			
<b>Overall Condition:</b>	F2 - Fair (Inspection within 2 Years)	<b>Requires Further Inspection:</b>	Yes
<b>Additional Observations:</b>	- Rail and rail footings need to be looked at. - Good candidate for rehab.		
<b>LEGEND:</b>			
<b>Condition Definitions:</b>			
1 - *Good - [discontinued code].	F2 - Fair (Inspection within 2 Years).	C - Unsafe (Closed to Public).	<b>Problem Definitions:</b>
2 - *Fair - [discontinued code].	F1 - Fair (Inspection within 1 Year).	U - Uninspectable.	N - No Problem.
3 - *Poor - [discontinued code].	P3 - Poor (Repair within 3 Years).	I - Inapplicable.	P - Possible Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor (Repair within 1 Year).		K - Known Problem.
G - Good (Inspection within 2 Years).	P - Poor (Immediate Repair).		NA - Not Applicable.
<b>Category Definitions:</b>			
Maint. - Maintenance.			
Eng. - Engineering.			
Office - Bridge Office.			
<b>PHOTO GUIDELINES:</b>			
<b>Inspection Photos:</b>			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> <li>● Any item which inspector feels should be documented by photograph</li> <li>● All items noted above as being P3, P1, P, or C</li> <li>● Any evidence of known ice, scour, debris, waterway problems</li> </ul>			
<b>INSPECTION PHOTOS</b>			

Department of Transportation and Works, Government of Newfoundland and Labrador 2018.