

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11062025-1	
Date: 10/21/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-192 - WINTERTON BROOK BRIDGE - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Scour and medium erosion along bottom length of abutments. Cracks with efflorescence, honey combing and hairline cracking in abutments. Wingwall on abutment #2 right hand side has crack with efflorescence, medium, narrow and hairline cracks, as well as erosion.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Light efflorescence in deck soffit (interior and exterior). Hairline and narrow cracks in soffit.				
DECK					
Condition:	F2 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F1 - Fair				
Comments:	Narrow pattern cracking with light efflorescence and some spalling in approach barriers. Rotten timber posts in approach rail system. Curbs require cleaning.				
HYDROLOGY					
Water Velocity:	n/a m/s	Ice Problem:	P - Possible Problem		
Water Depth:	n/a m	Scour Problem:	K - Known Problem		
Waterway:	01 - Adequate	Debris Problem:	NA - Not Applicable		
Comments:	N/A				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Replace missing two hazard signs.				
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Refer to BMS for detailed OSIM inspection.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.