

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B01132020-5	
Date: 1/13/2020	Inspected By: Lynch R / Burge H	Category: Eng. - Engineering	
BRIDGE INFORMATION			
Site:	TCH-037 - BISHOPS FALLS CNR OVERPASS WEST		
Route:		Overall Length:	45.6 m
Year Built:	1999	Est: No	Overall Width: 10 m
Year Last Rehab.:		Est: No	Roadway Width: 8.3 m
Region:	CENTRAL WEST	Sidewalk Width:	0 m
Jurisdiction:	Provincial	Clearance to R.D. or N.W.L.:	7 m
Type of Structure:	06 - Concrete Arch/TechSpan	Max Depth of N.W.L.:	0 m
Purpose of Structure:	01 - Highway Grade Separation	Spans:	
Type of Handrail:	04 - Steel Rail	<u>Span No.:</u>	<u>Length</u>
Roadway Surface:	02 - Asphalt	1	15.3
Alignment Vertical:	01 - Good	2	0
Alignment Horizontal:	01 - Good	3	0
Restrictions:	No	4	0
		5	0
		6	0
BRIDGE PHOTOS			
SUBSTRUCTURE			
Condition:	F2 - Fair	Bearings:	I - Inapplicable
		Bearing Seat:	I - Inapplicable
Comments:	Footings buried. Large trenches/potholes alongside footing #1 from ATV traffic.		
SUPERSTRUCTURE			
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable
Comments:	Evidence of leaking in top of structure at joints. Grass growing out of MSE headwalls/wing walls.		
DECK			
Condition:	F2 - Fair	Curbs:	I - Inapplicable
Hand Rail:	F2 - Fair	Roadway Condition:	I - Inapplicable
Approach Rail:	F2 - Fair		
Comments:	Newly paved on top. Roadway beneath has a few potholes.		
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	P - Possible Problem
Water Depth:	0 m	Scour Problem:	P - Possible Problem
Waterway:	03 - Not Applicable	Debris Problem:	N - No Problem
Comments:			

REPLACEMENT/REHABILITATION				
Next Rehab. Date:		Replacement Year:		
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0	
Recommendations:	Add more material to ATV road adjacent to roadway beneath structure			
OBSERVATIONS				
Overall Condition:	F2 - Fair	Requires Further Inspection:	No	
Additional Observations:	Flashing around cap buckled in places.			
LEGEND:				
Condition Definitions:		Problem Definitions:		Category Definitions:
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	N - No Problem.	Maint. - Maintenance.
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	P - Possible Problem.	Eng. - Engineering.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.	Office - Bridge Office.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.	
G - Good.	P - Poor.			
PHOTO GUIDELINES:				
Inspection Photos:				
Please provide photos using guidelines below:				
<ul style="list-style-type: none"> ● Any item which inspector feels should be documented by photograph ● All items noted above as being P3, P1, P, or C ● Any evidence of known ice, scour, debris, waterway problems 				
INSPECTION PHOTOS				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.