
	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B01202020-59	
Date: 9/24/2019	Inspected By: Lynch R / Martin L	Category: Eng. - Engineering	
BRIDGE INFORMATION			
Site:	3-044 - DARK COVE TICKLE BRIDGE, BRIGHTON		
Route:		Overall Length:	28.2 m
Year Built:	1991	Est: No	Overall Width: 9.6 m
Year Last Rehab.:		Est: No	Roadway Width: 8.6 m
Region:	CENTRAL WEST	Sidewalk Width:	0 m
Jurisdiction:	Provincial	Clearance to R.D. or N.W.L.:	2.5 m
Type of Structure:	01 - AASH to Girder	Max Depth of N.W.L.:	2.5 m
Purpose of Structure:	03 - Over Navigable Waters	Spans:	
Type of Handrail:	01 - Aluminum Rail	<u>Span No.:</u>	<u>Length</u>
Roadway Surface:	02 - Asphalt	1	16.8
Alignment Vertical:	01 - Good	2	0
Alignment Horizontal:	01 - Good	3	0
Restrictions:	No	<u>Span No.:</u>	<u>Length</u>
		4	0
		5	0
		6	0
BRIDGE PHOTOS			
			
SUBSTRUCTURE			
Condition:	F2 - Fair	Bearings:	F2 - Fair
		Bearing Seat:	F2 - Fair
Comments:	Bearings at abutment 2 in slight shear. Narrow vertical cracks in both abutments.		
SUPERSTRUCTURE			
Condition:	F2 - Fair	Expansion Joints:	F1 - Fair
Comments:	Joint dams damaged with missing concrete, curbs missing concrete as well. Joints rusty with scaling and full of winter sand but no evidence of leaking.		
DECK			
Condition:	F2 - Fair	Curbs:	F2 - Fair
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair

Approach Rail:	F1 - Fair		
Comments:	Potholes in deck and approaches at expansion joints. Curbs have spalling - rebar exposed at expansion joint 2; RHS. Plow damage on all guiderail with broken / rotten posts.		
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	N - No Problem
Water Depth:	0 m	Scour Problem:	N - No Problem
Waterway:	01 - Adequate	Debris Problem:	N - No Problem
Comments:	No navigation lights.		
REPLACEMENT/REHABILITATION			
Next Rehab. Date:		Replacement Year:	
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0
Recommendations:	Replace guiderail, repair curbs, asphalt and joint dams. Install navigation lights.		
OBSERVATIONS			
Overall Condition:	F2 - Fair	Requires Further Inspection:	No
Additional Observations:			
LEGEND:			
Condition Definitions:		Problem Definitions:	
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	N - No Problem.
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	P - Possible Problem.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.
G - Good.	P - Poor.		
Category Definitions:			
Maint. - Maintenance.			
Eng. - Engineering.			
Office - Bridge Office.			
PHOTO GUIDELINES:			
Inspection Photos:			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> ● Any item which inspector feels should be documented by photograph ● All items noted above as being P3, P1, P, or C ● Any evidence of known ice, scour, debris, waterway problems 			
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.