
	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B01202020-38	
Date: 9/4/2019	Inspected By: Lynch R / Martin L	Category: Eng. - Engineering	
BRIDGE INFORMATION			
Site:	3-077 - DOTING COVE BROOK CULVERT		
Route:		Overall Length:	16 m
Year Built:	1962	Est: No	Overall Width: 3.7 m
Year Last Rehab.:		Est: No	Roadway Width: 8 m
Region:	CENTRAL WEST	Sidewalk Width:	0 m
Jurisdiction:	Provincial	Clearance to R.D. or N.W.L.:	1.6 m
Type of Structure:	13 - Other	Max Depth of N.W.L.:	0.5 m
Purpose of Structure:	04 - Over Non-Navigable Waters		
Type of Handrail:	06 - None		
Roadway Surface:	02 - Asphalt	Spans:	
Alignment Vertical:	01 - Good	<u>Span No.:</u>	<u>Length</u>
Alignment Horizontal:	01 - Good	<u>Span No.:</u>	<u>Length</u>
Restrictions:	No	1	0
		2	0
		3	0
		4	0
		5	0
		6	0
BRIDGE PHOTOS			
			
SUBSTRUCTURE			
Condition:	F2 - Fair	Bearings:	I - Inapplicable
		Bearing Seat:	I - Inapplicable
Comments:	Some cracking in wing walls (medium). Some cracking (medium) in footing 2 RHS and footing 1 LHS.		
SUPERSTRUCTURE			
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable
Comments:	Open footed box. Rebar exposed on LHS top of headwall (spalled concrete).		
DECK			
Condition:	I - Inapplicable	Curbs:	I - Inapplicable
Hand Rail:	I - Inapplicable	Roadway Condition:	I - Inapplicable

Approach Rail:	I - Inapplicable		
Comments:			
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	N - No Problem
Water Depth:	0 m	Scour Problem:	N - No Problem
Waterway:	01 - Adequate	Debris Problem:	P - Possible Problem
Comments:	Could not see bottom in culvert, water dark.		
REPLACEMENT/REHABILITATION			
Next Rehab. Date:	2020	Replacement Year:	2020
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0
Recommendations:	Dam made of rocks located downstream of culvert.		
OBSERVATIONS			
Overall Condition:	F2 - Fair	Requires Further Inspection:	No
Additional Observations:	Cut and remove brush around the structure to avoid blockages.		
LEGEND:			
Condition Definitions:		Problem Definitions:	
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	N - No Problem.
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	P - Possible Problem.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.
G - Good.	P - Poor.		
Category Definitions:			
Maint. - Maintenance.			
Eng. - Engineering.			
Office - Bridge Office.			
PHOTO GUIDELINES:			
Inspection Photos:			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> ● Any item which inspector feels should be documented by photograph ● All items noted above as being P3, P1, P, or C ● Any evidence of known ice, scour, debris, waterway problems 			
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.