

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		<b>BRIDGE INSPECTION REPORT</b> <b>B01302024-1</b>	
Date: 11/21/2023		Inspected By: Strugnell		Category: Eng. - Engineering	
<b>BRIDGE INFORMATION</b>					
Site:		TCH-147 - GRAND FALLS/WINDSOR WEST OVERPASS-EASTBOUND - R			
<b>SUBSTRUCTURE</b>					
Condition:		F2 - Fair	Bearings:		F2 - Fair
			Bearing Seat:		F2 - Fair
Comments:		Bearings cleaned in 2021, narrow vertical cracks at both abutments full length.			
<b>SUPERSTRUCTURE</b>					
Condition:		F2 - Fair	Expansion Joints:		F2 - Fair
Comments:		New asphalt plug joints installed in 2023			
<b>DECK</b>					
Condition:		F2 - Fair	Curbs:		F2 - Fair
Hand Rail:		F2 - Fair	Roadway Condition:		F2 - Fair
Approach Rail:		F2 - Fair			
Comments:		Waterproof and paved based in 2021, surfaced paved in 2023, mill and fill approaches at 2023, cracking in end blocks, cracking in outside edge of curbs.			
<b>HYDROLOGY</b>					
Water Velocity:		n/a m/s	Ice Problem:		NA - Not Applicable
Water Depth:		n/a m	Scour Problem:		NA - Not Applicable
Waterway:		03 - Not Applicable	Debris Problem:		NA - Not Applicable
Comments:					
<b>REPLACEMENT/REHABILITATION</b>					
Next Rehab. Date:			Replacement Year:		
Antic. Rehab. Cost:		\$0	Replacement Cost:		\$0
Recommendations:					
<b>OBSERVATIONS</b>					
Overall Condition:		F2 - Fair	Requires Further Inspection:		No
Additional Observations:		snow fence installed on south side for the winter.			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.