

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B01302024-6	
Date: 11/21/2023		Inspected By: Strugnell		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-148 - GRAND FALLS/WINDSOR WEST OVERPASS-WESTBOUND - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	F2 - Fair	Bearing Seat:	F2 - Fair
Comments:	Narrow vertical cracks in both abutments				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	F2 - Fair		
Comments:	New asphalt plug joints installed 2023				
DECK					
Condition:	F2 - Fair	Curbs:	F2 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Waterproof and paved based in 2021, paved surface deck and approaches in 2023, cracking in curbs with efflorescence				
HYDROLOGY					
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Snow fence installed on North side for the winter.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.