

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B01172020-14	
Date: 11/5/2019	Inspected By: Lynch R / Martin L	Category: Eng. - Engineering	
BRIDGE INFORMATION			
Site:	3-023 - PETER'S ARM BROOK BRIDGE, #1, BOTWOOD		
Route:	350	Overall Length:	29.9 m
Year Built:	1966	Est: No	Overall Width: 8.8 m
Year Last Rehab.:		Est: No	Roadway Width: 7 m
Region:	CENTRAL WEST	Sidewalk Width:	0 m
Jurisdiction:	Provincial	Clearance to R.D. or N.W.L.:	4 m
Type of Structure:	01 - AASH to Girder	Max Depth of N.W.L.:	3 m
Purpose of Structure:	04 - Over Non-Navigable Waters	Spans:	
Type of Handrail:	02 - Concrete Rail	<u>Span No.:</u>	<u>Length</u>
Roadway Surface:	02 - Asphalt	1	24.8
Alignment Vertical:	01 - Good	2	0
Alignment Horizontal:	01 - Good	3	0
Restrictions:	No	4	0
		5	0
		6	0
BRIDGE PHOTOS			
			
SUBSTRUCTURE			
Condition:	F2 - Fair	Bearings:	F2 - Fair
		Bearing Seat:	F2 - Fair
Comments:	Narrow cracks in abutments. Minor spall on abutment 2 LHS footing.		
SUPERSTRUCTURE			
Condition:	F2 - Fair	Expansion Joints:	F2 - Fair
Comments:	Minor settlement at joint 2 RHS. Minor spalls and abrasion in dams.		
DECK			
Condition:	F2 - Fair	Curbs:	F2 - Fair
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair

Approach Rail:	F2 - Fair		
Comments:	Broken post abutment 2 LHS. Minor damage to hand rail. RHS rails have plow damage. Multiple cracks in underside of deck with efflorescence and stalactites.		
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	N - No Problem
Water Depth:	0 m	Scour Problem:	N - No Problem
Waterway:	01 - Adequate	Debris Problem:	N - No Problem
Comments:	Gabion basket at rock chute drain abutment 1 LHS is dislodged.		
REPLACEMENT/REHABILITATION			
Next Rehab. Date:		Replacement Year:	
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0
Recommendations:	Repair guiderail, posts and gabion basket		
OBSERVATIONS			
Overall Condition:	F2 - Fair	Requires Further Inspection:	No
Additional Observations:			
LEGEND:			
Condition Definitions:			
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	Problem Definitions:
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	N - No Problem.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	P - Possible Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor.		K - Known Problem.
G - Good.	P - Poor.		NA - Not Applicable.
Category Definitions:			
Maint. - Maintenance.			
Eng. - Engineering.			
Office - Bridge Office.			
PHOTO GUIDELINES:			
Inspection Photos:			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> ● Any item which inspector feels should be documented by photograph ● All items noted above as being P3, P1, P, or C ● Any evidence of known ice, scour, debris, waterway problems 			
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.