

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		<b>BRIDGE INSPECTION REPORT</b> <b>B01312024-6</b>	
Date: 10/27/2023		Inspected By: Strugnell/Hodder		Category: Eng. - Engineering	
<b>BRIDGE INFORMATION</b>					
Site:		3-034 - TRAVERSE BROOK BRIDGE - R			
<b>SUBSTRUCTURE</b>					
Condition:	F2 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	Strains and wet on corners of both abutments from sealant in joint, some bolts in bearing pads tipped during inspection				
<b>SUPERSTRUCTURE</b>					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Sealant missing in asphalt strip joints, girders ok				
<b>DECK</b>					
Condition:	F2 - Fair	Curbs:	I - Inapplicable		
Hand Rail:	I - Inapplicable	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Asphalt and approach rails ok, deck underside looks good				
<b>HYDROLOGY</b>					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
<b>REPLACEMENT/REHABILITATION</b>					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Clean out deck drains, replace sealants in strip joint				
<b>OBSERVATIONS</b>					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Deck drains blocked with sand and grass growing, no hazard markers, salmon river				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.