

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B07312024-9
Date: 7/31/2024	Inspected By: Lars/Sarah	Category: Office - Bridge Office
BRIDGE INFORMATION		
Site:	TCH-049 - WEST BOTTOM BROOK BRIDGE - R	
SUBSTRUCTURE		
Condition:	F2 - Fair	Bearings: F2 - Fair
		Bearing Seat: F2 - Fair
Comments:	Narrow vertical cracks observed in both abutment faces.	
SUPERSTRUCTURE		
Condition:	F2 - Fair	Expansion Joints: F2 - Fair
Comments:	Girders and asphalt joint both look ok.	
DECK		
Condition:	F2 - Fair	Curbs: F2 - Fair
Hand Rail:	F2 - Fair	Roadway Condition: F2 - Fair
Approach Rail:	F2 - Fair	
Comments:	Narrow cracking with efflorescence observed on south fascia.	
HYDROLOGY		
Water Velocity:	0 m/s	Ice Problem: N - No Problem
Water Depth:	0 m	Scour Problem: N - No Problem
Waterway:	01 - Adequate	Debris Problem: N - No Problem
Comments:	Sufficient riprap/scour protection.	
REPLACEMENT/REHABILITATION		
Next Rehab. Date:		Replacement Year:
Antic. Rehab. Cost:	\$0	Replacement Cost: \$0
Recommendations:		
OBSERVATIONS		
Overall Condition:	F2 - Fair	Requires Further Inspection: No
Additional Observations:		

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.