

Condition:	F2 - Fair	Curbs:	F2 - Fair
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair
Approach Rail:	F2 - Fair		
Comments:	Underside of deck has cracking perpendicular to the girders in 1 meter intervals with efflorescence seeping through. Concrete barrier hand rail has some vertical cracking. Concrete barriers near abutment 2 have honeycombing. Sand and salt build up laying on asphalt surface of concrete deck. Minor cracking in asphalt near plug joints.		
HYDROLOGY			
Water Velocity:	1 m/s	Ice Problem:	N - No Problem
Water Depth:	2.5 m	Scour Problem:	N - No Problem
Waterway:	01 - Adequate	Debris Problem:	N - No Problem
Comments:			
REPLACEMENT/REHABILITATION			
Next Rehab. Date:		Replacement Year:	
Antic. Rehab. Cost:	\$tbd	Replacement Cost:	\$tbd
Recommendations:			
OBSERVATIONS			
Overall Condition:	G - Good	Requires Further Inspection:	No
Additional Observations:			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.