

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		<b>BRIDGE INSPECTION REPORT</b> <b>B01242023-3</b>	
Date: 4/22/2022		Inspected By: Mike Fleming		Category: Eng. - Engineering	
<b>BRIDGE INFORMATION</b>					
Site:		TCH-092 - BALD MOUNTAIN BROOK BRIDGE - R			
<b>SUBSTRUCTURE</b>					
Condition:	F1 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	light to moderate hairline fractures noted on abutments and wingwalls. Light efflorescence deposits also noted on abutments.				
<b>SUPERSTRUCTURE</b>					
Condition:	F2 - Fair	Expansion Joints:	F1 - Fair		
Comments:					
<b>DECK</b>					
Condition:	F1 - Fair	Curbs:	F2 - Fair		
Hand Rail:	P3 - Poor	Roadway Condition:	F1 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Small amount of patched potholes adjacent to expansion joints. Handrail is damaged. Sections of light to moderate hairline fracturing and efflorescence deposits on deck soffit				
<b>HYDROLOGY</b>					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
<b>REPLACEMENT/REHABILITATION</b>					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
<b>OBSERVATIONS</b>					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Hazard Markers Missing. Pics on file.				