

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B05202025-13	
Date: 5/15/2025		Inspected By: L Christensen		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		4-016 - CANNIES BROOK BRIDGE - R450			
SUBSTRUCTURE					
Condition:		G - Good	Bearings:		I - Inapplicable
			Bearing Seat:		I - Inapplicable
Comments:					
SUPERSTRUCTURE					
Condition:		G - Good	Expansion Joints:		I - Inapplicable
Comments:					
DECK					
Condition:		G - Good	Curbs:		G - Good
Hand Rail:		G - Good	Roadway Condition:		F2 - Fair
Approach Rail:		G - Good			
Comments:					
HYDROLOGY					
Water Velocity:		0 m/s	Ice Problem:		N - No Problem
Water Depth:		0 m	Scour Problem:		N - No Problem
Waterway:		01 - Adequate	Debris Problem:		N - No Problem
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:			Replacement Year:		
Antic. Rehab. Cost:		\$0	Replacement Cost:		\$0
Recommendations:					
OBSERVATIONS					
Overall Condition:		G - Good	Requires Further Inspection:		No
Additional Observations: Replaced in 2020					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.