

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	<b>BRIDGE INSPECTION REPORT</b> <b>B02062023-5</b>	
<b>Date:</b> 5/2/2022	<b>Inspected By:</b> Mike Fleming	<b>Category:</b> Eng. - Engineering	
<b>BRIDGE INFORMATION</b>			
<b>Site:</b>	4-110 - DOWNEY BRIDGE		
<b>Route:</b>		<b>Overall Length:</b>	24.3 m
<b>Year Built:</b>	1984	<b>Est:</b> No	<b>Overall Width:</b> 10 m
<b>Year Last Rehab.:</b>		<b>Est:</b> Yes	<b>Roadway Width:</b> 9 m
<b>Region:</b>	WEST COAST/NORTHERN		<b>Sidewalk Width:</b> 0 m
<b>Jurisdiction:</b>	Provincial	<b>Clearance to R.D. or N.W.L.:</b>	1.8 m
<b>Type of Structure:</b>	03 - Reinforced Concrete Beam/Slab		<b>Max Depth of N.W.L.:</b> 0 m
<b>Purpose of Structure:</b>	03 - Over Navigable Waters		<b>Spans:</b>
<b>Type of Handrail:</b>	01 - Aluminum Rail		<u>Span No.:</u> <u>Length</u> <u>Span No.:</u> <u>Length</u>
<b>Roadway Surface:</b>	02 - Asphalt	1	12.9    4    0
<b>Alignment Vertical:</b>	01 - Good	2	0    5    0
<b>Alignment Horizontal:</b>	01 - Good	3	0    6    0
<b>Restrictions:</b>	No		
<b>BRIDGE PHOTOS</b>			
<b>SUBSTRUCTURE</b>			
<b>Condition:</b>	G - Good	<b>Bearings:</b>	G - Good
		<b>Bearing Seat:</b>	G - Good
<b>Comments:</b>			
<b>SUPERSTRUCTURE</b>			
<b>Condition:</b>	F1 - Fair	<b>Expansion Joints:</b>	I - Inapplicable
<b>Comments:</b>	One section of spalling and cracking with exposed steel on the bottom of the upstream fascia girder due to a above deteriorated drain.		
<b>DECK</b>			
<b>Condition:</b>	G - Good	<b>Curbs:</b>	G - Good
<b>Hand Rail:</b>	G - Good	<b>Roadway Condition:</b>	F1 - Fair
<b>Approach Rail:</b>	F1 - Fair		
<b>Comments:</b>	Deck drains are deteriorating and leaking on the below girders. Approach rail damaged, not structural, and not attached to end blocks, missing Michigan shoe inserts. Light amount of potholes and cracking noted at the interface of the approaches and deck.		
<b>HYDROLOGY</b>			
<b>Water Velocity:</b>	0 m/s	<b>Ice Problem:</b>	P - Possible Problem
<b>Water Depth:</b>	0 m	<b>Scour Problem:</b>	P - Possible Problem

<b>Waterway:</b>	01 - Adequate	<b>Debris Problem:</b>	P - Possible Problem
<b>Comments:</b>			
<b>REPLACEMENT/REHABILITATION</b>			
<b>Next Rehab. Date:</b>	2023	<b>Replacement Year:</b>	
<b>Antic. Rehab. Cost:</b>	\$0	<b>Replacement Cost:</b>	\$0
<b>Recommendations:</b> Remove winter sand from along curbs, replace drains, repair girder, install structural rail, and resurface.			
<b>OBSERVATIONS</b>			
<b>Overall Condition:</b>	F1 - Fair	<b>Requires Further Inspection:</b>	No
<b>Additional Observations:</b> Pics on file			
<b>LEGEND:</b>			
<b>Condition Definitions:</b>		<b>Problem Definitions:</b>	
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	N - No Problem.
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	P - Possible Problem.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.
G - Good.	P - Poor.		
<b>Category Definitions:</b>			
Maint. - Maintenance.			
Eng. - Engineering.			
Office - Bridge Office.			
<b>PHOTO GUIDELINES:</b>			
<b>Inspection Photos:</b>			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> <li>● Any item which inspector feels should be documented by photograph</li> <li>● All items noted above as being B, F, P, or C</li> <li>● Any evidence of known ice, scour, debris, waterway problems</li> </ul>			
<b>INSPECTION PHOTOS</b>			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2024.