

GOVERNMENT OF
NEWFOUNDLAND
AND LABRADOR
Department of Transportation and Infrastructure

BRIDGE INSPECTION REPORT B01212021-2

Date: 1/21/2021 Inspected By: Mike Fleming Category: Eng. - Engineering **BRIDGE INFORMATION** Site: 4-046 - ROCKY BROOK BRIDGE, REIDVILLE 41.4 m Route: **Overall Length:** 1973 Year Built: Est: No **Overall Width:** 8.84 m Year Last Rehab.: 1993 Est: No Roadway Width: 7.32 m Region: WEST COAST/NORTHERN Sidewalk Width: 0.76 m Clearance to R.D. or Jurisdiction: Provincial 0 **m** N.W.L.: 01 - AASH to Girder Max Depth of N.W.L.: $0 \, \mathbf{m}$ Type of Structure: Purpose of Structure: 03 - Over Navigable Waters Spans: 02 - Concrete Rail Type of Handrail: Span No.: Length Span No.: Length 01 - Concrete Roadway Surface: 1 33.5 4 02 - Adequate 2 0 5 0 Alignment Vertical: 3 0 6 0 01 - Good Alignment Horizontal: No Restrictions: **BRIDGE PHOTOS SUBSTRUCTURE** Condition: G - Good Bearings: G - Good G - Good **Bearing Seat:** Comments: **SUPERSTRUCTURE** G - Good F2 - Fair Condition: **Expansion Joints:** Comments: **DECK** G - Good G - Good Condition: Curbs: Hand Rail: G - Good G - Good **Roadway Condition:** F2 - Fair Approach Rail: Moderate settling noted on approaches with patch potholes along the expansion joints. Light to moderate Comments: delamination and spalling with exposed light to moderately corroded rebar on the deck soffit. Patched sections on the deck are starting to separate. **HYDROLOGY** 0 m/s N - No Problem Water Velocity: Ice Problem: N - No Problem Water Depth: $0 \, \mathbf{m}$ Scour Problem: 01 - Adequate N - No Problem

Waterway:			Debris Problem:			
Comments:						
REPLACEMENT/REHAB	ILITATION					
Next Rehab. Date:	2021		Replacement Yea	r:	2021	
Antic. Rehab. Cost:	\$0		Replacement Cos	it:	\$0	
Recommendations:						
OBSERVATIONS						
Overall Condition:	G - Good		Requires Further Inspection:		No	
Additional Observations:	Inspection pictures are o	on file.				
LEGEND: Condition Definitions: 1 * Good - [discontinued code]. 2 * Fair - [discontinued code]. 3 * Poor - [discontinued code]. 4 * *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling any nem wnich inspector any nem wnich inspector and the provide photos and the providence of known ice	F2 - Fair. F1 - Fair. F3 - Poor. P1 - Poor. P - Poor. ess below: ess spoula pe documented by pneing P3, P1, P; or C	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. otograpn	Public).	Problem De N - No Prok P - Possibl K - Known NA - Not Ap	olem. e Problem. Problem.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.
INSPECTION PHOTOS						

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.