Newfoundland Labrador	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDO	BRIDGE INSPECTION REPORT B01142021-25 Category: Eng Engineering				
Date: 11/7/2020	Inspected By: Mike Flei							
BRIDGE INFORMATION								
Site:	4-026 - ST. PAUL'S INLET	T BRIDGE						
Route:				Overall Leng	gth:	94.8 <b>m</b>		
Year Built:	1970 <b>Est:</b> No			Overall Width:		10.3 <b>m</b>		
Year Last Rehab.:	2004 <b>Est:</b> Yes			Roadway Width:		7.7 <b>m</b>		
Region:	WEST COAST/NORTHERN			Sidewalk Width:		0 <b>m</b>		
Jurisdiction:	Provincial			Clearance to R.D. or N.W.L.:		5 <b>m</b>		
Type of Structure:	10 - Callender-Hamilton or Other Stress Truss Bridge			Max Depth of N.W.L.:		0 <b>m</b>		
Purpose of Structure:	03 - Over Navigable Waters			Spans:				
Type of Handrail:	04 - Steel Rail			<u>Span No.:</u>	<u>Length</u>	<u>Span No.:</u>	<u>Length</u>	
Roadway Surface:	04 - Steel			1	94.8	4	0	
Alignment Vertical:	01 - Good			2	0	5	0	
Alignment Horizontal:	01 - Good			3	0	6	0	
Restrictions:	No							
BRIDGE PHOTOS								
SUBSTRUCTURE								
Condition:	G - Good Bearings		Bearings:	G - G	Good			
		E	Bearing Seat:	G - G	Good			
Comments:	Minor fractures observed	on abutment faces	and sidewalls.					
SUPERSTRUCTURE								
Condition:	G - Good Expansion Joint			s: G - Good				
Comments:	Light corrosion noted on girders and bracing.							
DECK								
Condition:	G - Good	(	Curbs:	G - G	Good			
Hand Rail:	G - Good	F	Roadway Condition	n: G-G	Good			
Approach Rail:	G - Good							
Comments:	Transverse cracking and	minor amount of po	otholes on approach	es adjacent te	o expansio	n joints.		
HYDROLOGY								
Water Velocity:	0 m/s Ice Problem:		ce Problem:	N - N	lo Problem			
Water Depth:	0 m Scou		Scour Problem:	N - N				
Waterway:	01 - Adequate	[	Debris Problem:	N - N	lo Problem			
Comments:								

REPLACEMENT/REHABILITATION								
Next Rehab. Date:	2021		Replacement Yea	<b>ır:</b> 2021				
Antic. Rehab. Cost:	\$0		Replacement Cos	st: \$0				
Recommendations:								
OBSERVATIONS								
Overall Condition:	G - Good		Requires Further Inspection:	No				
Additional Observations:	Hazard markers missir	ng. Inspection pictur	es on file.					
LEGEND: Condition Definitions: 1 - *Good - [discontinued code]. 2 - *Fair - [discontinued code]. 3 - *Poor - [discontinued code]. 4 - *Unsafe - [discontinued code]. G - Good. PHOTO GUIDELINES: Inspection Photos: Please provide photos using guideling Any tiem which inspector n Any tiems noted above as bo Any evidence of known ice	F2 - Fair. F1 - Fair. P3 - Poor. P1 - Poor. P - Poor. P - Poor. P - Poor. P or C Bing P3, d2, P or C scour, debris, waterway proble	C - Unsafe (Closed to U - Uninspectable. I - Inapplicable. onotograpn	Public).	Problem Definitions: N - No Problem. P - Possible Problem. K - Known Problem. NA - Not Applicable.	Category Definitions: Maint Maintenance. Eng Engineering. Office - Bridge Office.			
INSPECTION PHOTOS								

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.