

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B05242024-7	
Date: 5/24/2024		Inspected By: L Christensen		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-162 - CATARACTS RIVER BRIDGE - R91			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Substructure looks to be in fair condition from below. Hard to access full footprint. Some spalling present and rebar visible.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	P3 - Poor		
Comments:	Expansion joints jammed with material, cleaning required.				
DECK					
Condition:	P3 - Poor	Curbs:	I - Inapplicable		
Hand Rail:	I - Inapplicable	Roadway Condition:	P3 - Poor		
Approach Rail:	P3 - Poor				
Comments:	Damaged guard rail				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	No major issues observed. Footings seem to be in good condition, some concrete spalling and exposed rebar, please see inspection photos				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.