

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B02182025-8	
Date: 2/13/2025		Inspected By: T Upshall / M Button		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		1-063 - COOTE'S POND BRIDGE NO.1 - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	No observed defects to precast recon block wing walls.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Narrow vertical crack in east and west precast deck fascia at mid span.				
DECK					
Condition:	F2 - Fair	Curbs:	F2 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:	*Assumed condition of deck top (covered in asphalt) based on condition of deck soffit below. Hairline vertical and pattern/crazing cracking in barrier walls.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:	Aggradation observed beneath structure.				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:	2040	Replacement Year:	2100		
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Structure replaced in 2021 with new precast rigid frame.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.