

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11132024-4	
Date: 11/13/2024		Inspected By: Lars/Sarah		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-009 - GUNRIDGE ROAD BRIDGE (BAY BULLS) - R			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	New SW wing wall. Narrow map cracking with some med efflorescence on all wing walls except the new. Medium/large vertical cracks and efflorescence under embedded steel beam in frame leg. Assumed steel beam is not structural, it is extremely corroded.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Narrow cracks with efflorescence on facia. Old steel I beams left embedded in abutments extremely corroded.				
DECK					
Condition:	F1 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F1 - Fair		
Approach Rail:	F2 - Fair				
Comments:	New guiderail, end blocks, concrete barrier and inspection paths.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Recent rehab completed and work completed looking good.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.