

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11042025-2	
Date: 11/4/2025		Inspected By: Megan/Heidi		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-104 - PADDY'S POND UNDERPASS - R1			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Large spall with exposed reinforcement in abutment #1 wingwall on left hand side. Disintegration also present. Hairline, narrow and medium cracks in abutments and wingwalls.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:	Severe spalls and wide horizontal crack in exterior soffit and fascia. Cracks with efflorescence and rust staining of exterior soffit. Low cover spalls and rust staining of interior soffit. Hairline and narrow cracks in both soffits.				
DECK					
Condition:	F1 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F1 - Fair		
Approach Rail:	P3 - Poor				
Comments:	Abutment #1 RHS guide rail detached from barrier. Small spalls, medium to hairline cracks in curb. Medium potholes in areas of the wearing surface. Area of exposed concrete deck at approach #1. Transverse cracks and raveling of asphalt surface.				
HYDROLOGY					
Water Velocity:	n/a m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	n/a m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:	N/A				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Refer to detailed OSIM inspection in BMS.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.