

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B01282026-4	
Date: 1/23/2026		Inspected By: T Upshall / M Button		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		1-274 - RATTLING BROOK BRIDGE - R93			
SUBSTRUCTURE					
Condition:	G - Good	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	No observed defects to substructure.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	I - Inapplicable		
Comments:	Hairline angular cracks with light efflorescence observed in the corner of the exterior precast rigid frame travelling towards haunch.				
DECK					
Condition:	G - Good	Curbs:	I - Inapplicable		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	G - Good				
Comments:	*Assumed condition of deck top (covered in asphalt) based on condition of deck soffit below. Hairline vertical cracks in barrier walls with light efflorescence.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:	Bedrock was removed at the outlet during construction in 2023 to change river alignment. No issues were observed during inspection. All rip rap in good condition.				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	G - Good	Requires Further Inspection:	No		
Additional Observations:	Structure replaced since last inspection. Construction completed in August 2024.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.