

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11132024-15	
Date: 11/13/2024		Inspected By: L. Christensen/D.Burns		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-138 - SHORES COVE BRIDGE - R10-35			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	U - Uninspectable		
		Bearing Seat:	U - Uninspectable		
Comments:	Very steel side slopes. Minor cracks with EFF on wing walls with patches of severe deterioration. EFF from bottom of abutments leaking onto bedrock. Minor honeycombing on faces of abutments. Bridge seems to have an older and newer section. Older abutment shave severe EFF on face with more water draining through drains.				
SUPERSTRUCTURE					
Condition:	P3 - Poor	Expansion Joints:	U - Uninspectable		
Comments:	Some exposed reinforcement in double TEE webs. Water evidently passing through deck and double TEE webs. Concrete deterioration and skin reinforcement visible around deck drain.				
DECK					
Condition:	F1 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F1 - Fair	Roadway Condition:	F1 - Fair		
Approach Rail:	F1 - Fair				
Comments:	Curbs covered in debris.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Hazard markers missing. Monitor girder deterioration, especially around drain.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.