

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B11052025-3	
Date: 10/30/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		TCH-114 - HOLYROOD ACCESS OVERPASS-WESTBOUND - R1			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	I - Inapplicable		
Comments:	Medium cracks and hairline to narrow cracks in abutments. Wet pattern map cracking in wingwalls and inclined legs.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:					
DECK					
Condition:	F1 - Fair	Curbs:	P3 - Poor		
Hand Rail:	F2 - Fair	Roadway Condition:	F1 - Fair		
Approach Rail:	P3 - Poor				
Comments:	Some low cover spalls and cracks with efflorescence in soffit interior. Wet pattern map cracking and hairline to narrow cracking of soffit interior and exterior. Wide longitudinal crack in soffit exterior. Some wide cracks with efflorescence in soffit exterior. Wide cracks with efflorescence and wet pattern map cracking in barriers. Potholes in asphalt. Area of exposed concrete deck.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	Refer to BMS for detailed OSIM inspection.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.