

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10232025-2	
Date: 10/23/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		1-209 - WESTERN POND BROOK BRIDGE - R			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	F1 - Fair		
Comments:	Mild erosion along bottom length of abutments. Cracks with efflorescence (1m and 2 m lengths) in Abutment #2. All wingwalls have long wide vertical cracks (full height). Some spalling at top of wingwall for abutment #1 right hand side. Medium scaling and hairline cracks in wingwalls and abutments.				
SUPERSTRUCTURE					
Condition:	P3 - Poor	Expansion Joints:	I - Inapplicable		
Comments:	Exterior fascia on north side of structure has severe disintegration and spalling. Deck facias on north and south sides have cracks with efflorescence.				
DECK					
Condition:	P3 - Poor	Curbs:	I - Inapplicable		
Hand Rail:	P1 - Poor	Roadway Condition:	P3 - Poor		
Approach Rail:	I - Inapplicable				
Comments:	Missing rail on south side replaced by timber post/rail (unstable). Hairline cracking and spalled areas in concrete handrail. Exposed deck at approach. Spalls and cracks with efflorescence in soffit.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	01 - Adequate	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	P3 - Poor	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.