

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B04132026-4	
Date: 11/25/2025		Inspected By: Devin Thistle		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		3-047 - BAY D'ESPOIR CAUSEWAY BRIDGE - R361			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	Minor cracking in mid/higher abutment face. Spalling underside of deck between girders 3 & 4 on abutment 2 side. Small minor hairline cracks in wingwalls & girders and efflorescence present in abutments. Medium cracking in piers downstream.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	F2 - Fair		
Comments:	Minor hairline cracking on girders.				
DECK					
Condition:	F2 - Fair	Curbs:	F2 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:					
HYDROLOGY					
Water Velocity:	rapid m/s	Ice Problem:	N - No Problem		
Water Depth:	high m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Rehab done this year (2025).				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.