

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B03312026-1	
Date: 12/1/2025		Inspected By: Devin Thistle		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		3-029 - MIGUEL'S BROOK BRIDGE - R360			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	Pattern cracking in wingwalls with efflorescence. Hairline cracking in patches on abutments and wingwalls				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	F2 - Fair		
Comments:	Hairline cracking in girders. South end block downstream has plow damage. Hairline cracking in soffits with efflorescence. Joints full of sand and Hairline cracking in dams,				
DECK					
Condition:	F2 - Fair	Curbs:	F2 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Winter sand build up at curbs				
HYDROLOGY					
Water Velocity:	medium m/s	Ice Problem:	N - No Problem		
Water Depth:	medium m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Salmon river - new rehab in 2021				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.