

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B03312026-2	
Date: 11/20/2025		Inspected By: Devin Thistle		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		3-038 - SOUTHEAST BROOK BRIDGE - R361			
SUBSTRUCTURE					
Condition:		F2 - Fair	Bearings:		F2 - Fair
			Bearing Seat:		F2 - Fair
Comments:					
SUPERSTRUCTURE					
Condition:		G - Good	Expansion Joints:		G - Good
Comments: Cracking in joint dams minor. Sand in expansion joints					
DECK					
Condition:		G - Good	Curbs:		G - Good
Hand Rail:		G - Good	Roadway Condition:		G - Good
Approach Rail:		G - Good			
Comments: Minor hairline cracks in curb					
HYDROLOGY					
Water Velocity:		slow m/s	Ice Problem:		N - No Problem
Water Depth:		high m	Scour Problem:		N - No Problem
Waterway:		01 - Adequate	Debris Problem:		N - No Problem
Comments: abutments out of water at time of inspection rip rap ok					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:			Replacement Year:		
Antic. Rehab. Cost:		\$0	Replacement Cost:		\$0
Recommendations:					
OBSERVATIONS					
Overall Condition:		F2 - Fair	Requires Further Inspection:		No
Additional Observations: Rehabilitated in 2024					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.