

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B01312024-4	
Date: 7/7/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		3-185 - STONEY BROOK BRIDGE - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	Some hairline and medium cracking with efflorescence in abutments/wingwalls. One 0.4 m x 0.6 m spall observed in abutment 2 on RHS.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	I - Inapplicable		
Comments:	Modular bridge components in excellent condition.				
DECK					
Condition:	F2 - Fair	Curbs:	F1 - Fair		
Hand Rail:	G - Good	Roadway Condition:	F1 - Fair		
Approach Rail:	G - Good				
Comments:	Fair deck wearing surface. Deck soffits in good condition. Handrails and posts in excellent condition. Steel on steel deck railing system post near abutment 2 LHS has missing bolt requiring replacement.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:	N/A				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Steel on steel deck railing system post near abutment 2 LHS has missing bolt requiring replacement. Deck surface requires cleaning.				
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	Salmon river. Refer to detailed OSIM inspection.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.