

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07162025-3	
Date: 7/10/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		3-151 - WOODEN BRIDGE #3 - R363			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	I - Inapplicable		
		Bearing Seat:	F1 - Fair		
Comments:	Creosote timbers in cribs have split/cracked and are showing signs of deterioration. New members added to timber cribbing.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	I - Inapplicable		
Comments:					
DECK					
Condition:	F2 - Fair	Curbs:	F2 - Fair		
Hand Rail:	I - Inapplicable	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Timber deck repaired with new members. Posts, rail, curb and wearing surface recently replaced.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:	Low water levels during inspection, no visible scouring.				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Install missing hazard signs on each side of the approach as per standard. Replace the bridge with a buried structure.				
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:	No hazard signs are visible at the approaches.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2025.