

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B07172025-2	
Date: 4/30/2024		Inspected By: Mike Fleming		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		4-035 - BARASWAY BROOK BRIDGE - R470			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	F1 - Fair		
		Bearing Seat:	F1 - Fair		
Comments:	One bearing pad severely deteriorated at the Eastern upstream fascia girder, part of the girder is resting directly on the bearing seat causing mild to moderate spalling at the seat.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	G - Good		
Comments:	Rehab completed in 2001				
DECK					
Condition:	G - Good	Curbs:	G - Good		
Hand Rail:	G - Good	Roadway Condition:	G - Good		
Approach Rail:	G - Good				
Comments:	Rehab completed in 2001. One section of mild spalling noted on curb soffit with exposed and corroded bar; one section of mild delamination on deck soffit with exposed and corroded rebar. Significant winter sand accumulation on and adjacent to the curbs.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	N - No Problem		
Water Depth:	0 m	Scour Problem:	N - No Problem		
Waterway:	01 - Adequate	Debris Problem:	N - No Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	No Bridge hazard markers noted. Pics on file.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.