

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B09092025-5	
Date: 9/2/2025		Inspected By: Megan/Heidi		Category: Office - Bridge Office	
BRIDGE INFORMATION					
Site:		4-126 - BLANCHE BROOK BRIDGE - R460			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	U - Uninspectable		
		Bearing Seat:	U - Uninspectable		
Comments:	Abutments in good condition. Some hairline cracking. Wide crack with rust and crack with efflorescence. Mild erosion. Medium cracks noted in abutment #2. Two bearings in poor condition. Others not inspectable. Hairline cracking in wingwalls. Wide crack with spalling related to damaged post in abutment #2 wingwall right hand side. Fair and poor areas in wingwalls.				
SUPERSTRUCTURE					
Condition:	G - Good	Expansion Joints:	F2 - Fair		
Comments:	Girders in excellent condition, some low cover spalls. Suspected leakage at seal.				
DECK					
Condition:	G - Good	Curbs:	F2 - Fair		
Hand Rail:	F2 - Fair	Roadway Condition:	F2 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Deck requires cleaning.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	01 - Adequate	Debris Problem:	NA - Not Applicable		
Comments:	N/A				
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Replace missing (1) and/or raise low hazard signs (3). Repair eroded embankment/slope protection at abutment #2 left hand side. Perform deck cleaning.				
OBSERVATIONS					
Overall Condition:	G - Good	Requires Further Inspection:	No		
Additional Observations:	Refer to BMS for detailed OSIM inspection. Utility noted on left side.				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.