

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10092024-9	
Date: 9/25/2024		Inspected By: Scott Wight		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-178 - COOPER'S BROOK BRIDGE - R			
SUBSTRUCTURE					
Condition:		F2 - Fair	Bearings:		I - Inapplicable
			Bearing Seat:		I - Inapplicable
Comments:		Spalling noted on both abutments. Efflorescence noted on both abutments.			
SUPERSTRUCTURE					
Condition:		G - Good	Expansion Joints:		I - Inapplicable
Comments:					
DECK					
Condition:		G - Good	Curbs:		F2 - Fair
Hand Rail:		G - Good	Roadway Condition:		F2 - Fair
Approach Rail:		G - Good			
Comments:		Minor damage to the east curb. Minor end block damage. Asphalt cracking at the deck approach.			
HYDROLOGY					
Water Velocity:		0 m/s	Ice Problem:		N - No Problem
Water Depth:		0 m	Scour Problem:		P - Possible Problem
Waterway:		01 - Adequate	Debris Problem:		N - No Problem
Comments:		Minor scouring at NE corner. Shoulder of roadway washing out on the U/S south approach.			
REPLACEMENT/REHABILITATION					
Next Rehab. Date:			Replacement Year:		
Antic. Rehab. Cost:		\$TBD	Replacement Cost:		\$TBD
Recommendations:					
OBSERVATIONS					
Overall Condition:		G - Good	Requires Further Inspection:		No
Additional Observations:		Three missing hazard markers. Accumulation of winter sand along curb.			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.