

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10242025-3	
Date: 8/21/2025		Inspected By: C.Spencer		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-102 - CORNER BROOK INDUSTRIAL UNDERPASS - R			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	paved slope damage. cracking on underside of deck above bearing				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	F1 - Fair		
Comments:	expansion joints leaking, scouring are rehabilitated sections on underside of deck.				
DECK					
Condition:	F1 - Fair	Curbs:	P3 - Poor		
Hand Rail:	F1 - Fair	Roadway Condition:	P3 - Poor		
Approach Rail:	F1 - Fair				
Comments:	Curb buried under winter sand. Minor damage to rail, potholes present, Minor damage to rail.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.