

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B10242025-5	
Date: 9/2/2025		Inspected By: C.Spencer		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		TCH-115 - DEER LAKE UNDERPASS - R			
SUBSTRUCTURE					
Condition:	F1 - Fair	Bearings:	F2 - Fair		
		Bearing Seat:	F2 - Fair		
Comments:	Minor cracking in abutment. Undermining of concrete pavers lining slope/rebar ties visible.				
SUPERSTRUCTURE					
Condition:	F1 - Fair	Expansion Joints:	F1 - Fair		
Comments:	Snowplow damage to south expansion joint. Joint is leaking. Minor corrosion visible on girders. Deck drains plugged, moderate corrosion at the 90 of the drain. Minor spalling on curb fascia				
DECK					
Condition:	F1 - Fair	Curbs:	F2 - Fair		
Hand Rail:	G - Good	Roadway Condition:	F1 - Fair		
Approach Rail:	F2 - Fair				
Comments:	Damage to end block, exposed rebar. Some minor potholes.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable		
Water Depth:	0 m	Scour Problem:	NA - Not Applicable		
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:					
OBSERVATIONS					
Overall Condition:	F1 - Fair	Requires Further Inspection:	No		
Additional Observations:					

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.