

		GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure		BRIDGE INSPECTION REPORT B01052026-3	
Date: 11/4/2024		Inspected By: Mike Fleming		Category: Eng. - Engineering	
BRIDGE INFORMATION					
Site:		4-066 - DRIBBLE BROOK BRIDGE - R			
SUBSTRUCTURE					
Condition:	F2 - Fair	Bearings:	U - Uninspectable		
		Bearing Seat:	U - Uninspectable		
Comments:	Light/minor scouring and erosion along abutment footings. Minor spalling on abutment walls.				
SUPERSTRUCTURE					
Condition:	F2 - Fair	Expansion Joints:	I - Inapplicable		
Comments:					
DECK					
Condition:	F1 - Fair	Curbs:	F1 - Fair		
Hand Rail:	F1 - Fair	Roadway Condition:	P3 - Poor		
Approach Rail:	P3 - Poor				
Comments:	Approach rail is severely damaged; Handrail and end blocks are lightly damaged. Spalling noted on curb fascia.				
HYDROLOGY					
Water Velocity:	0 m/s	Ice Problem:	K - Known Problem		
Water Depth:	0 m	Scour Problem:	K - Known Problem		
Waterway:	01 - Adequate	Debris Problem:	K - Known Problem		
Comments:					
REPLACEMENT/REHABILITATION					
Next Rehab. Date:		Replacement Year:			
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0		
Recommendations:	Replace approach and hand rail; repair curbs and spalling on abutment walls. Waterproof and resurface deck. Install hazard markers				
OBSERVATIONS					
Overall Condition:	F2 - Fair	Requires Further Inspection:	No		
Additional Observations:	No Hazard Markers. Pics on File				

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2026.